

NOTE:
REMOVE RAILROAD TIES,
REGRADE AND REPLACE
WITH ROCK RETAINING
WALLS WHERE NEEDED



SHADE SYSTEMS EXAMPLE



SUGGESTED
REALIGNMENT OF
ADA RAMPS

NOTE:
REMOVE RAILROAD TIES
AND REGRADE TO
ACCOMMODATE SIDEWALK
EXTENSION AND ENTRY TO
HISTORIC COURTYARD.



ENSCRIPTED PAVERS
DOCUMENTING HISTORIC
MOMENTS, TIMELINE, KEY
PLAYERS IN THE
COMMUNITY, ETC.



AMAZON.COM
PULL DOWN PROJECTOR
SCREEN CEILING
INSTALLATION DESIGN
100" INCH TO BE
MOUNTED AT WEST ARBOR

GENERAL NOTES:

- THE SITE NEEDS TO BE REGRADED FOR PROPER DRAINAGE.
- ONCE PLAN IS ESTABLISHED, A PROPER IRRIGATION SYSTEM FOR SITE NEEDS TO BE INSTALLED.
- SITE LACKS A "SENSE OF ARRIVAL". SUGGESTIONS FOR THE ENTRY SPACE INCLUDE:

- PLANTING BEDS AT MAIN ENTRY SIGN
- PLANTING/SHADE TREES ALONG THE ENTRY DRIVE
- SUGGESTED STREETSCAPE IMPROVEMENTS ALONG S. TRAVIS

STREET INCLUDE:

- ESTABLISHMENT OF PEDESTRIAN SIDEWALKS FROM HWY79.
- ESTABLISHMENT OF SHADE TREES ALONG S. TRAVIS
- RESTORATION OF INDIVIDUAL HOMES CURBSIDE APPEAL
- INTEGRATION OF "HISTORIC WALK" WITH USE OF PAVERS

MILL AVENUE

PLANTING AT
GEORGE HILL PATTERSON
COMMUNITY CENTER
ENTRY SIGN



NORTH

0 5 10 20 30 50
ARCHITECTURE SCALE: 3/32" = 1'-0"